	Туре	e #	Hits	Search Text	DBs	Time Stamp	Comments	ErrorDefinition	ro
1	BRS	L 4	3292	422/100.ccls. or 436/180.ccls. or (73/864.13,864.16,86 4.17).ccls.	USPA T; US-P GPUB; ; EPO; JPO; DERW ENT	2004/06/1 5 23:08			0
2	BRS	L 5	7925 48	(piezoelectric\$5 or piezo or magnet\$6 or thermal\$3 or pneumatic\$6) near10 (actuat\$4 or pulse\$2 or generat\$5 or element\$1 or driv\$3)	GPUB; EPO;	2004/06/1 5 23:14			0
3	BRS	:	2	5 same (piston\$1 or plunger\$2 or rod\$1 or syringe\$1 or barrel\$1)	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2004/06/1 5 23:15			0
4	BRS	L 7	156	4 and 6		2004/06/1 5 23:15)

	Туре	L #	Hits	Search Text	DBs	Time Stamp	C o m m e n t s	D e f	Er ro rs
5	BRS	F 8	93	7 and (wash\$3 or rins\$3)	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2004/06/1 5 23:15			0
6	BRS	L 9	103	7 and (wash\$3 or rins\$3 or flush\$3)	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2004/06/1 6 00:00			0
7		L 1 0	53	7 not 9	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/06/1 6 00:00			0